



Firmware Upgrade Procedure

NOTE: This procedure only applies to Honeypot 2009.03.3 and older.

1. Acquire a copy of the **calibration** file(s) for your gauge(s) from <http://rty.ca/calibration/>.

You may download multiple calibration files at once in a ZIP file if you know the required serial numbers, by entering them in the online form. If you have to upgrade the firmware on more than one gauge, this is the recommended method.

2. Acquire a copy of the **newest firmware** for your gauge(s) from <http://rty.ca/project/kodiak/>.

Please note that the Kodiak Cub firmware package contains firmware for all models of gauges (such as the KC1 and KC2).

3. Connect the gauge to Honeypot, and select the **Tools -> Upload Firmware** menu option.

*You will be prompted to select the firmware file to upload. Please make sure you select the file matching your gauge model. **Failure to do so can result in damage to the gauge.***

4. From Honeypot, select the **Tools -> Erase sectors** menu option and enter "**1**" to erase the first sector.

Once this operation has completed, the gauge serial number will read as "4294967295".

5. From Honeypot, select the **Tools -> Upload calibration** menu option and select the calibration file matching the gauge serial number.

The serial number is printed on the outside of the gauge housing.